

COMPLETE LIST OF MTI REPAIR SERVICES

PART REPAIR

PART NUMBER	DESCRIPTION
99-AIO-901	CPU PC BOARD
99-80103	CPU PC BOARD
99-80071	CPU PC BOARD
99-AIO-900	TRACK I/O BOARD
99-80122	TRACK I/O BOARD
99-80072	TRACK I/O BOARD
99-80076	CONNECTOR INTERFACE BOARD
99-80073	DISPLAY BOARD
99-80082	HEATER/ CONTROLLER BOARD
99-80039	INDEXER INTERFACE BOARD
99-80074	KEYBOARD FRONT PANEL
99-80075	MOTHER BOARD
99-80105	MOTHER BOARD
99-80089	SENSOR BOARD (INTERRUPTIVE OR REFLECTIVE)
99-80054	TRANSISTOR BOARD
99-80170-01	VACUUM SENSOR BOARD
99-80146	VACUUM SENSOR BOARD
99-80102	VAPOR PRIME OVEN BOARD
99-80065	WAFER SENSOR BOARD
99-80157	ARM ASSEMBLY PC BOARD

MODULE REPAIR / REBUILD

BARBER COLEMAN TEMPERATURE CONTROLLER REPAIR (MODEL 580, 590)
CTD IMMERSION CIRCULATOR REPAIR
CTD IMMERSION CIRCULATOR MODIFY (INCL. ALARM PCB & HARNESS)
INDEXER ASSEMBLY REPAIR
INDEXER ASSEMBLY REBUILDS (NEW MOTORS, COATED PLATFORMS, ETC.)
INDEXER ASSEMBLY UPGRADE TO CAP. SENSOR AND MAJOR REBUILD
MILLIPORE PUMP CONTROLLER REPAIR
POWER SUPPLY ASSEMBLY REPAIR

*Repair services for other boards, modules, and obsolete items are also available.
Please call for pricing.